# 2021 PHRF-NB Membership/Rating Certificate

This certificate expires on April 30, 2022, or upon change of ownership, whichever comes first.

**Certificate status: Renewed** 

Ratings		
56	69	
Spinnaker	Non-Spinnaker	

#### **Administrative Data**

Name:	Danforth, Murray
Address:	Privacy Protected
Email:	
Primary Phone:	
Secondary Phone:	
Yacht Club:	New Bedford YC

#### **Boat Measurements**

<b>I:</b> 42.74	<b>J:</b> 12.43	<b>LOA:</b> 33.13		
<b>P:</b> 42.64	<b>E:</b> 15.42	LWL: 31.72		
<b>ISP:</b> 44.33	<b>SPL:</b> 14.27	Draft: Max 6.89		
Py:		Ey:		
<b>Beam:</b> 11.3	2	Displacement: 6600		
Rig Type: S		Rig: Fractional		
Keel Weight: 2420		Keel Material: Steel/lead		
		Other Ballast: Water-66 gal		
		1561 lbs/03 degrees incline		
Mast Material: Carbon		Spinnaker Type(s):		
		Asymmetrical Symmetrical		
Asymmetri	Asymmetrical Spinnaker Tacked To: apole			

#### **Variables**

Prop. Type: Folding	Engine: Inboard
perture <b>Rudder:</b> Spade	Prop. Install: Aperture
Keel: Fin Keel	# of Blades: 2
Keel: Fin Keel	# of Blades: 2

#### **Yacht**

Yacht Name: Flying Turtle	Sail Number: 27
<b>Designer:</b> Marc Lombard	
Manufacturer: Beneteau	Model: Beneteau Figaro 2
Hull Serial Number: FR-	Date Manufactured:
BEYB6082C707	2007
Other Ratings:	Date Last Rated:

#### Sails

Headsails to be used		Mainsail	Mainsail Measurements		
(LP%)		МНВ	0.06		
Headsail 1	110	MUW	3.48		
Headsail 2	100	MTW	6.23		
Headsail 3	0	MHW	10.24		
Headsail 4	0	MQW	13.12		

### Spinnakers to be used

Spin #	JC	SMG	Foot	Luff	Leech
Spin 1	14.27	23.62	23.62	43.96	43.96
Spin 2	14.27	21.32	21.32	42.32	42.31
Spin 3	14.27	23.42	23.62	45.43	40.35
Code 0					

**Headsail Credit:** Roller Furling

## **Comments/Modifications**

Twin Rudders;Fin covers shaft from exit of hull to cutless bearing;carbon fiber mast, aluminum boom, rod rigging, Dyneema back stay. Production ODR Hull # 82; sails & materials restricted..Water ballast 561 lbs= -6 2011-Alum. Boom replaced with carbon fiber boom=No Change in rtg.2014:Code 0 tacked to deck - noted. 2015: noted that sailor felt penalty for ballast was excessive- told him we were using our standard calculations in determination. 2021-Undersized spin +4. Revision #1 Roller furling was added +3, plus ISP Mod. -2

## **Committee Use Only**

PHRF #: 15719				
Base Rating	57	Non-Spin Adj.	17	
Genoa Spin Adj.	0	Genoa Non-Spin Adj.	0	
Mainsail Adj.	0	Furling Adj.	3	
Spin. Area Adj.	4	Whisker Pole Adj.	0	
Prop. Adjustment	0			
Mast Adj.	0	Misc. Adj.	-8	
Committee Signature		Date		
Katherine Rotsky		05/07/2021		